

Description:

Vacuum Table

1. Consists of a typically flat rigid surface in which exists small holes to evacuate air from under a workpiece, as to apply varying vacuum from between the desired workpiece and table to maintain a clamping force.
2. To make the soft printing materials like leather more smooth and level, so as to get the best printing result.



