

Description:

Vacuum Table

1. Consists of a typically flat rigid surface in which exists small holes to evacuate air from under a workpiece, as to apply varying vacuum from between the desired workpiece and table to maintain a clamping force.
2. To make the soft printing materials like leather more smooth and level, so as to get the best printing result.





To

make the soft printing materials like leather more smooth and level, so as to get the best printing result.